



JON M. HUNTSMAN, JR.
Governor


GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
April 20, 2011

Reviewed: 

Mine Name: Torrey Sandstone Quarry	Permit Number: M0550016
Operator Name: Star Stone Quarries, Inc.	Inspection Date: April 20, 2011
Inspector(s): Wayne Western	Time: 9:10 – 10:00 AM
Other Participants:	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The current bond is for \$35,000.00 and the bond escalation date is April 18, 2011. The permit fees have been paid for 2010.


The site showed no sign of recent activity. There are several large pieces of equipment on site including backhoe, rock saw, loader and water truck.

The site appeared stable, there were no problems.

Conclusions and Recommendations:

The Division should update the bond.

Inspector's Signature




WHW:

cc: (OPERATOR

Sue_Fivecoat@blm.gov


O:\M055-Wayne\M0550016-Torrey_Quarry\inspections\Insp-042020111.doc



Equipment and stockpiles



Equipment and stockpiles



Active pit



Active pit